


10 Firmware update

New firmware can solve some problem, improve printing quality and stability.


Updating firmware by flow the steps below:

1. Select "File" -> "Firmware Update"



pic 77 Firmware update

2. Attention: **You should update flash data first** (File name: Flash_FWx.x.x.x.brn)
3. And repeat the process above to update main program (File name: tps_FWx.x.x.x.brn)
4. **DO NOT** power off until updating complete, and T10 will restart after updating process finished.



pic 78 Updating message